

## Apple II Workstation Card: No Apple IIGS Support (2/97)

| Revised:<br>Security:   |  |
|---|--|
| Apple II Workst   | cation Card: No Apple IIGS Support (2/97)                      |
| =========   |  |
| Apple II Workst   | tation Card: Apple IIGS Support (2/97)                         |
| Article Created: 03 August 1989<br>Article Reviewed/Updated: 12 February 1997 |  |
| TOPIC   |  |
| This article di   | iscusses the Apple II Workstation card and Apple IIGS support. |
| DISCUSSION  |  |

The Apple II Workstation Cards is not supported in the Apple IIGS because of the following reasons.

- \* When the Apple II Workstation Card is installed, only ProDOS 8 applications can run. The Workstation Card tells the server that it is an Apple IIe. Therefore, it will not work in a ProDOS 16 network environment. Typically, this means only the first 64 K of memory will be used.
- \* The Workstation Card is not fully tested in this configuration and it is not supported by Apple.

Article Change History:

12 Feb 1997 - Reviewed for technical accuracy, revised formatting.

Copyright 1989-97, Apple Computer, Inc.

Tech Info Library Article Number: 4000